Sheet1

Recharge Test Data Record

Core Boring Number CB-RS-XX-5

Date Of Test 11-17-99

Test Performed by Nathan Bryan

Ground Water Level 4.0-ft

Casing Size 2.0-in

Casing Depth 125' of 2" PVC, 5' of 2" PVC Screen (0.10 Escreto)

Hole Diameter at point of test 2 5/8" hole w/ Sand (620 & 3065)

				A	B		C	D	E	F
From Depth Elevation	To Depth Elevation	Time Start	Time Stop	Total Time	Depth to Ground Water before test	Depth to Ground Water after test	Stickup above Ground	Total Head	Total Water Injected	Gallons Per Minute
Feet (bgs)	Feet (bgs)	Min	Min	Min	Feet (bgs)	Feet (bgs)	Feet	Feet B+C	Gal	GPM E/A
125.0	130.0	0	5.0	5.0	4.0	4.2	5.0	9.0	0.14	0.03

NOTES: 1. Record water lake with the water maintained at the top of casing.
2. Water depth must be measured immediately before the recharge test.
3. Water depth shall be recorded after test, and noted if changed.
4. Typical test time is 6 minutes.

The confining layer was not reached. The recharge test was in silty, slightly clayey fine sand.

DRILLING LOG — SAD

1. PROJECT: North Lake Belt Impoundment Area
2. LOCATION: C-9 Camp
3. DRILLING AGENCY: U.S. Drilling
4. HOLE NO. (FOR MULTIPLE HOLES): CBRS-XX-5
5. NAME OF DRILLER: J.C. Moffett
6. DIRECTION OF HOLE: ☒ VERTICAL ☐ INCLINED ____ DEG. FROM VERT.
7. THICKNESS OF OVERBURDEN: 35-ft
8. DEPTH DRILLED INTO ROCK: 95-ft
9. TOTAL DEPTH OF HOLE: 130-ft

10. DISTRICT: Jacksonville District — SHEET 1 OF 5 SHEETS
11. SIZE AND TYPE OF BIT: 2-7/8" bit - 3" casing
12. MANUFACTURER'S DESIGNATION OF DRILL: CME-55 Truck Mounted
13. TOTAL NO. OF OVERBURDEN SAMPLES: 23 — UNDISTURBED: 1
14. TOTAL NUMBER CORE BOXES:
15. ELEVATION GROUND WATER: 4'9" 3.19 M
16. DATE HOLE: STARTED 11-15-99 — COMPLETED 11-17-99
17. ELEVATION TOP OF HOLE:
18. TOTAL CORE RECOVERY FOR BORING: 61 %
19. SIGNATURE OF INSPECTOR: Mike H. Bryan

ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV.	TYPE OF SAMPLE	REMARKS (Drilling time, water loss, depth of weathering, voids, etc.)
	0		LIMESTONE, porous, incompetent, hard.			Casing 0-1 - 0.02" 1-2 - 0.02" 2-3 - 0.02" 3-4 - 0.02"
	15		REC = 9"/19			
	20		RQD = 0%			
	25		competent, porous, hard.			4-5 - 0.07" 5-6 - 0.35"
	30		REC = 24"/50			6-7 - 0.54"
	40		RQD = 6.5"/14			7-8 - 0.28"
	45		gray fine to medium sand, silty, clayey between 7'-8' ± 2"-3". (in voids).			4' of 3" ϕ casing installed.
	90		competent, porous, hard.			8-9 - 0.16" 9-10 - 1.35"
	95		REC = 24"/40			10-11 - 0.54" 11-12 - 0.45"
	120		RQD = 12"/20			12-13 - 7.30"
	125		Sandy silt fossil voids between 12'-14' ± 2"-4" medium sand.			8' of 3" ϕ casing installed.
	150		REC = 44"/73			13-14 - 8.54" 14-15 - 0.87"
	155		RQD = 26"/43			15-16 - 0.22" 16-17 - 0.23"
	160		fairly continuous, slightly porous, moderately hard.			17-18 - 2.20"
	180		competent, porous, mod. hard.			13' of 3" ϕ casing installed.
	185		REC = 24"/40			18-19 - 1.15" 19-20 - 0.20"
	200		RQD = 0%			20-21 - 0.13" 21-22 - 0.38"
	225		(continued)			22-23 - 0.07"
						18' of 3" ϕ casing installed.

0 — circulation lost
1.5 — casing installed for circulation return.
4.5
6.0
7.5
9.0
10.5
12.0 — hard layer from 12'-14' bgs.
13.5
15.0
16.5
18.0
19.5
21.0

CHG FORM 1836 PREVIOUS EDITION ARE OBSOLETE.

PROJECT: N. Lake Belt Impoundment Area — HOLE NO. CB-25-XX-5

DRILLING LOG (Cont Sheet)

N. Lake Belt Impoundment Area — Jacksonville District — Hole No. CB-RS-46-S

ELEVATION	DEPTH	RECOVERY	CLASSIFICATION OF MATERIALS	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS
	20		LIMESTONE - See Previous 18'-23', Pg-1.			Box Counts
22.5			REC = 51"/85 RQD = 34.5"/58 Fairly continuous, moderately hard, slightly porous.			21.0 still loosing water 11-15-99
25.5						22.5
27.0						24.0
28.5			REC = 29"/48 RQD = 11.5"/19 competent, hard, porous.			25.5
30.0						27.0
31.5						28.5
33.0			REC = 58"/97 RQD = 48"/80 Fairly continuous, moderately hard, slightly porous.			30.0
34.5						31.5
36.0						33.0
37.5			REC = 58.5"/98 RQD = 28.5"/48 Fairly continuous, moderately hard, slightly porous.			34.5
39.0						36.0
40.5						37.5
42.0			REC = 51"/85 RQD = 42"/70 fairly continuous, moderately hard, slightly porous.			39.0
43.5						40.5 1-ft drop of core barrel between 40'-42' for 1 sec.
45.0						42.0
46.5						43.5
48.0			REC = 13"/22 RQD = 0% Incompetent hard, porous. (continued)			45.0
49.5						46.5 hard layer @ 48' bgs - 49' bgs & @ 49'-50' bgs
						48.0
						49.5

ENG FORM 1836-A

N. Lake Belt Impoundment Area CB-RS-46-S

DRILLING LOG (Cont Sheet)

N. Lake Belt Impoundment Area — Jacksonville District — Hole No. CB-BS-wlk-5

ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS	% CORE RECOV.	SOIL OR SAMPLE NO.	REMARKS
	49.5		LIMESTONE, Same as previous 48'-50' bgs.			50-51 - 0.07" / 51-52 - 0.22" / 52-53 - 0.02" / 48' of 3" ϕ casing installed. / 53-54 - 0.90" / 54-55 - 0.28" / 55-56 - 0.15" / 56-57 - 0.22" / 57-58 - 0.31" / 53' of 3" ϕ casing installed. / 58'-59 - 0.05" / 59-60 - 0.02" / 60-61 - 0.06" / 61-62 - 0.03" / 62-63 - 0.27" / 58' of 3" ϕ casing installed. / 63-64 - 0.19" / 64-65 - 0.03" / 65-66 - 0.02" / 66-67 - 0.02" / 67-68 - 0.83" / 63' of 3" casing installed. / 68'-69 - 0.29" / 69-70 - 0.34" / 70-71 - 0.21" / 71-72 - 0.30" / 72-73 - 0.12" / 68' of 3" ϕ casing installed. / 73-74 - 0.02" / 74-75 - 0.21" / 75-76 - 6.30" / 76-77 - 2.08" / 77-78 - 4.20" / 78' of 3" ϕ casing installed. / 78-79 - 0.30" NR / 79-80 - 0.52" NR
	51.0		competent, hard, porous. REC = 28"/40 RQD = 4"/6 Sand filled solution holes between 52.5'-58' bgs. (Trace silty fine sand)			
	52.5					
	54.0					
	55.5					
	57.0					
	58.5		REC = 9"/15 RQD = 0% very hard cemented sandy rounded fragments from 62.5-64.0 Ft. bgs. Incompetent, hard, Porous.			
	60.0					
	61.5					
	63.0		REC = 15"/25 RQD = 8"/13 Incompetent, hard, porous.			
	64.5					
	66.0					
	67.5		REC = 58"/97 RQD = 18"/30 Fairly continuous, moderately hard, slightly porous.			
	69.0					
	70.5					
	72.0					
	73.5		competent, hard to moderately hard, porous. Very hard from 76'-78' bgs. REC = 21"/40 RQD = 0% fine to coarse silty sand filled holes from 77'-78' bgs. (continued)			very zone hard layer @ 75'-78' bgs.
	75.0					
	76.5					
	78.0					
	79.5					

still loosing circulation

ENG FORM 1836-A

N. Lake Belt Impoundment Area — Jacksonville District — Hole No. CB-RS-XX-5

Elevation	Depth	Legend	Classification of materials (Description)	% Core Recovery	Box or Sample No.	Remarks (Drilling time, water loss, depth weathering, etc. if significant)
78.0			LIMESTONE, continuous, moderately hard, slightly porous.			Coring
79.5			REC = 57"/95			78-79 - 0.30"
			RQD = 31"/82			79-80 - 0.52"
81.0						80-81 - 0.33"
						81-82 - 0.15"
82.5						82-83 - 0.38"
						78' of 3" ϕ casing installed.
84.0			Incompetent, hard, porous			83-84 - 0.20"
						84-85 - 0.24"
85.5			REC = 20"/33			85-86 - 0.02"
			RQD = 17"/28			86-87 - 0.02"
87.0						87-88 - 0.02"
						88' of 3" ϕ casing installed.
88.5			LIMESTONE, gravel size recovery, trace fine to med. silty sand.	6"/33	1	Split Spoon
90.0				4"/22	2	See Note! →
91.5			Rollerbit Overdrill - No Recovery			
93.0			REC = 10"/33			Coring
			RQD = 0%			93-94 - 0.21"
			Incompetent, porous, hard.			94-95 - 0.21"
			SAND, white, silty, large gravel size limestone fragments. Due to much shell fragments & limestone fragments	4"/50	3	95-95.5 - 0.10"
96.0				35"/19	4	
97.5			No large gravel size limestone fragments from 98.5'-104.5' bgs.	12"/66	5	98' of 3" ϕ casing installed.
99.0				11"/44	6	
100.5				NRD		
102.0				10"/56	7	recvd from 101.5'-103' bgs.
103.5				0.5"/3	8	103' of 3" ϕ casing installed.
105.0			SAND, silty, dark grey, fine sand.	18"/100	9	
			(continued)			

Blow counts
78.0
79.5
81.0
82.5
84.0
85.5
87.0
88.5
90.0
91.5
93.0
94.5
96.0
97.5
99.0
100.5
102.0
103.5
105.0

Initially thought to be sand. Probable large cavity or sand layer. No sand recovery.

11-16-99

Note: Spoon did not refuse, very poor recovery w/ spoon. Driller decided to core from 93' for better recovery based on experience.

94.5': coring stopped @ 95.5'. Probable sand.

Probable sand, white, silty.

MD of RUN

ENG FORM 1836-A

N. Lake Belt Impoundment Area CB-RS-XX-5

N. Lake Belt Impoundment Area — Raiford District

Elevation	Depth	Graphic Log	Classification of Materials	% Core Recovery	Blow Counts per 6 in.	Remarks
1040	0		SAND, grey-dark grey, silty, clayey, fine sand.	15" / 83	10	
1035	5			18" / 100	11	
1030	10			18" / 100	12	
1025	15			18" / 100	13	
1020	20			18" / 100	14	
1015	25			8" / 44	15	
1010	30			18" / 100	16	
1005	35			18" / 100	17	
1000	40			18" / 100	18	
995	45			18" / 100	19	
990	50			18" / 100	20	
985	55			18" / 100	21	Recharge Test from 125'-130' bgs.
980	60			18" / 100	22	
975	65		Trace Shell & shell fragments.	24" / 100	23	2-ft spoon from 125'-127' bgs.
970	70	HQ TUBE	Tube Bent at 2'-3" @ end. cut before sealing.			
965	75		Boring Terminated @ 130' bgs.			

11-17-99

Blow Counts: 6, 8, 10, 9, 8, 10, 5, 6, 10, 12, 12, 14, 14, 12, 12, 12